



Tree Survey Reference	British Standard Category	Identified for removal in Phase 1A South*
G061	B2	Large group of trees. Some trees feature minor defects such as stem asymmetry, crown, mild deadwood. Maximum DBH crown diameter given in schedule. Accurate DBH crown diameter on drawing. Limited TOPO data. Individual constituent trees poor but coalesce to create a notable landscape feature. 4 x Norway maple, 1 x Red oak, 1 x Lime, 1 x Ash and 1 x Sorbus to be removed from this group.
G098	C2	Large group of trees. All trees feature significant defects. Weak unions on scaffold limbs. Included bark. Trees with landscape value but significant defects. Small group of trees. All trees feature minor defects. Weak unions on scaffold limbs. Bark wounds on base of stem. Bark wounds on main stem. Poor form. Individual constituent trees poor but coalesce to create a notable feature. 1 x Lime to be removed from this group.
G099	C2	Highways tree. No indicators of disease/decay/structural defects. Minor deadwood. Restricted root zone. A tree with slight impaired condition.
T343	B2	Table identifies only those trees and groups of trees affected by the proposals in or within 10m of the application boundary. Commentary from Arboricultural Impact Assessment/Tree Survey Schedule May 2015 (Revision C)

BUILDING DESIGN PARTNERSHIP SHALL HAVE NO RESPONSIBILITY FOR ANY USE, REUSE OR MISUSE OF THIS INFORMATION. ALL DIMENSIONS SHOULD BE CHECKED ON SITE. DO NOT SCALE FOR CONSTRUCTION PURPOSES. DRAWING ERRORS OR OMISSIONS SHOULD BE BROUGHT TO THE ATTENTION OF BUILDING DESIGN PARTNERSHIP AT THE ADDRESS SHOWN BELOW.

**NOTES**

Plan to be read in conjunction with following documents:  
 Tree survey, Arboricultural Impact Assessment, Arboricultural Method Statement and Tree Protection Plan in accordance with BS5837: 2012 prepared by Haydens Arboricultural Consultants  
 Survey of Schedule 9 Listed Invasive Weed Species prepared by Ecolat Environmental

All tree works should adhere to current best practice detailed within BS 5827:2012 (Trees in relation to design, demolition and construction - recommendations) For removal of existing trees within tree protective fencing areas and/or within Root Protection Areas of other trees, refer to Haydens Arboricultural Consultants' document listed above

The position, condition and dimensions of the trees are based on a site survey undertaken on 12/02/14  
 The original of this drawing was produced in colour - a monochrome copy should not be relied upon  
 All existing trees to be removed as approved under Condition 27.1 for Phase 1(A/N) RMA are not shown on this plan. This plan only shows additional trees to be removed within 10 metres of the Phase 1(A/S) RMA boundary.

**LEGEND**

- Boundary of School Lane Reserved
- Matters Application
- Trees and Vegetation to be Retained
- Trees and Vegetation to be Removed under Phase 1A South Application



FIRST ISSUE FOR INFORMATION YL MS 22/10/15



16 Brixton Square  
 London EC4V 3DF  
 United Kingdom  
 T +44 (0)207 812 8000  
 F +44 (0)207 812 8399  
 www.bdp.com

**BRENT CROSS PHASE 1A SOUTH**

PROJECT NO: P2007004  
 SCHOOL LANE  
 TREE REMOVAL PLAN

DATE: 22/10/15  
 DRAWN BY: 1:3000 @A3  
 CHECKED BY: 1:3000 @A3  
 PROJECT NO: (97)LP005